

NOTES:

- 1) PIPE PENETRATION MUST BE CLEAN AND FREE OF CONTAMINATION OR LOOSE PARTICLES
- 2) PIPE PENETRATIONS MUST BE PRIMED WITH THE APPROPRIATE PRIMER BEFORE APPLYING LIQUID MEMBRANE
- 3) GAPS AT THE BASE OF THE PIPE MUST BE FILLED IN PRIOR TO MEMBRANE FLASHING
- REFER TO LAM CAN 1-0 FOR AN ANGLE TRANSITIONAL WITH CRACKS AS REQUIRED.
- 5) PAINTERS TAPE OR METAL FOIL TAPE SHALL BE USED AT THE TOP OF THE PIPE FLASHING TO ENSURE A UNIFORM FINISH AND WILL BE REMOVED IMMEDIATELY AFTER MEMBRANE APPLICATION
- 6) FOR ALTERNATE FLASHING DETAIL SEE LAM CAN 7-2B
- 7) SEALANT IS A MAINTENANCE ITEM AND IS NOT COVERED UNDER THE ROOFPRO WARRANTY

