

NOTES:

- 1) NEW OR EXISTING WOOD NAILERS SHALL BE ATTACHED ACCORDING TO THE DESIGNER OF RECORD., THE NATIONAL BUILDING CODE OF CANADA, LOCAL CODE, OR INSURANCE REQUIREMENTS, WHICHEVER IS MORE STRINGENT.
- 2) SEALANT IS A MAINTENANCE ITEM AND IS NOT COVERED UNDER THE ROOFPRO WARRANTY.
- 3) NON STRUCTURAL CRACKS MUST BE FILLED PRIOR TO SIKALASTIC APPLICATION
- 4) REFER TO LAM CAN 1-0 FOR AN ANGLE TRANSITIONAL WITH CRACKS.



AS A MANUFACTURER OF COMSTRUCT, SIRCA MANDA INC., SIRCA, PROVIDES GENERIC DETAILS AS A GENERAL GUIDE FOR INFORMATION PROPEDSES ONLY. SIRCA MAY REVIEW DETAILS PREPARED BY THE CONSULTANT, ARCHITECT, ENGINEER AND/ON DESIGN PROFESSIONAL PRACTICES AND JUDGEMENT AND SHOULD NOT BE RELIED UPON FOR THAT PROJECT. THE GENERIC DETAILS AMPLOY REVIEW OF DETAILS AND FOR THE PROJECT. THE GENERAL BY SIRCA AND IS NOT BEING CONDUCTED IN LIEU OF SOUND CONSULTANT, ARCHITEC ENGINEER AND/OR DESIGN PROFESSIONAL PRACTICES AND JUDGEMENT AND SHOULD NOT BE RELIED UPON FOR THAT PURPOSE. SIKA ASSUMES NO LIABILITY WITH RESPECT TO THE DESIGN OF THE ROFINITY, ARCHITECT, ENGINEER AND/OR DESIGN PROFESSIONAL PRACTICES AND JUDGEMENT AND SHOULD NOT BE RELIED UPON FOR THAT PURPOSE. SIKA ASSUMES NO LIABILITY WITH RESPECT TO THE DESIGN OF THE REPROSENSIBILITY FOR THE PERSENDA OF THE PERSENDAL OF THE SYSTEM. FOR THE PERSENDAL OF THE SYSTEM A PRACTICULAR PARTICULAR PARTICULA